

FMTV A1P2....

Protective Cap PROTECTS Hydraulic Fluid!

WHEN IT'S RAINING
OUTSIDE, MY ELECTRIC
HYDRAULIC POWER UNIT
(EHPU) NEEDS PROTECTION
FROM THE WATER!



FMTV A1P2 trucks were fielded without the protective (or breather) cap, NSN 5340-01-590-0054, installed on the EHPU. As a result, the EHPU fluid is getting contaminated with water. That can lead to failing cab lift hydraulic components.

But there's an easy fix to prevent future contamination and the trouble it brings. Make sure your truck's EHPU breather is covered with its cap.

Breather cap



Breather
without cap
installed

